



## **Notice Inviting Tender:**

**For IIM (Metal House) at AQ-13/4, Sector-V, Salt Lake City, Kolkata-91**

**(IIM Mural Rectification Work - Auditorium and External Front & Side Facade)**

### Description of the Mural works

The mural work at IIM needs some rectifications and modification as per existing work order. The details are given in Annexure I, Annexure II and Annexure III.

Refer PDF : IIM Mural (Annexure I to Annexure III)

### Current status of the Mural works

The Artist/Vendor should visit the site ([Metal House, Plot 13/4, Block AQ, Salt Lake, and Sec V Kolkata 700091](#)) for proper understanding of the mural status.

### Quotation for completing the unfinished Mural work:-

| SL | Work   | Quantity      | Rate | Amount in Rs. |
|----|--|---------------|------|---------------|
| 1  | Side Facade Mural – Refer Annexure I<br><u>Light specification: Side</u><br>12 watts - hoarding LED lights       | as per actual |      |               |
| 2  | Front Facade Mural- Refer Annexure II<br><br>Front Light specification : Front<br>12 watts - hoarding LED lights | as per actual |      |               |
| 3  | Auditorium Mural – Refer Annexure III  | as per actual |      |               |

Note: Payments will be made as per applicable.

Proforma For Technical Bid: The details of the company are as under:

|  |  |
|--|--|
| Name of the firm Contact Address with Telephone/Fax  |  |
| Tax/Income Tax Registration No.  |  |
| Tax/Income Tax Clearance Certificate PAN and Service Tax Details   |  |
| GST Registration #   |  |
| No. of employees   |  |
| Type of Ownership  |  |
| Ownership details  |  |
| Details of experience (the name and contact details of the clients where you have already implemented same kinds of restrictions). |  |

Financial Bid Criterion

1. Rates must be quoted in figures & words in INR with all levies and taxes.
2. Late receipt of bids – 5<sup>th</sup> November 2022
3. Provide Pan and GST Numbers as applicable.

Eligibility Conditions

- a) The Artist/Firm should have experience of at least 5 years.
- b) The firm should be having PAN & GST number (Preferable) and it should be registered with the concerned tax authorities.
- c) It should not be black listed by the government department or any PSU. An undertaking in this regard may be attached with Technical Bid.

Terms and Conditions

1. There shall be no escalation in the price during the entire contract period, however, either of the parties may if so decides, shall have the option to terminate its contract by giving the other party prior written notice of 1 month.
2. The Secretary General, on part of the IIM reserves the right to reject or ignore, any or all quotations and shall not be bound itself to accept the lowest offer.
3. If the modification is done by more than one vendor, the permitted time given per mural modification (Auditorium, External Front & Side Facade) is one week. If all mural modifications are given to a single vendor, then two weeks is the maximum mural modification completion time.
4. Lights and fixtures quoted should be equal or better (in specifications & make) than the ones already fitted in murals.
5. Last date of submission of quotation : 5<sup>th</sup> November 2022
6. Please submit the tenders to the below-mentioned E-Mail Address.

Addressed to: Mr. Kushal Saha, Secretary General

E-Mail ID: [kushal.saha@iim-india.net](mailto:kushal.saha@iim-india.net)

# IIM Mural Rectification Work - Auditorium and External Front & Side Facade

The Indian Institute of Metals

Metal House Plot 13/4, Block AQ, Salt Lake, Sec V Kolkata 700091

## Contents

|    |                                |    |
|----|--------------------------------|----|
| A. | Side Facade Mural – Annexure I | 2  |
| B. | Front Facade Mural-Annexure II | 7  |
| C. | Auditorium Mural -Annexure III | 10 |

## A. Side Facade Mural - Annexure I

- 1) The gap between the lines is quite small. It should be increased. (Image - 1)
- 2) The words "THE INDIAN INSTITUTE OF METALS" are not in the horizontal center. Needs to be rectified. [Two endpoints being A & B as shown in the (Image -1) ]
- 3) No proper gapping between the letters at both the sides. Needs to be rectified. (Image - 1).
- 4) "I" is not visible properly in the word Institute. (Image - 1)



Image 1

5) Pencil lines are visible which need to be erased. (Image - 2)



Image 2

6) The aluminium pipe covering (of drain pipe) should be seamlessly covered with the existing mural design as indicated. (Image – 3)



Present scenario

Image – 3

- 7) All the 3 lights installed should be on the top of the IIM building as shown in the image below to ensure uniform lighting of the whole Mural. Rod stands are to be installed.  
(Refer Image-4 and 5 attached below)

3 Light specification: Side  
3 no. of 12 watts - hoarding LED lights






Image 5

## B. Front Facade Mural- Annexure II

1) The central circular piece to be removed. (Refer Image 1)



For the central circular piece (8 nos. of interlocking hollow square section) to be installed as shown in the image below. (Refer Image 2)

### 4 Central Circular



Central circular piece

Image 2



8 no.s of interlocking hollow square sections of light weight alloy coated for weather proofing

- 2) When we stand facing the IIM building, the left-hand side murals (3 pieces) are not in the central alignment with each other. It needs to be rectified.
- 3) Shadows are cast on the front facade murals when lights are lit. Presently, only one light is installed under each front facade mural. There should be 2 lights in each area-either top and bottom, or right and left side. As a result, an additional light needs to be installed in each front facade mural segment. (Refer Image 3)
- 4) Additional lights to be installed for the IIM logo. (Refer Image-3 and 4)



The shadows cast on the front facade murals are not acceptable. There should be 2 lights in each area-either top and bottom, or right and left side.

Lights to be installed for IIM logo.

Image 3

6 Central logo



Back lit signage to highlight the IIM logo, centrally positioned, making the front façade more welcoming for visitors.

Reference images




Exterior Scone lighting to highlight walls.


Image 4

### C. Auditorium Mural - Annexure III

All the rectifications to be done on the mural in the Metal House Auditorium are listed below.



2) The Nail is visible in the Mural



3) Joint on the Mural is visible.  
Has an irregular edge.




4) Joint on the Mural is visible.  
Has an irregular edge.



5) Irregular edge




6) Golden paints are not done properly.  
Light and dark shades visible




7) Dirt on the mural. Nail Visible



8) Golden painting is not done properly.  
Light and dark shades are visible all  
over the mural.





9) Present scenario - Welding finishes are not presentable.  
 The image of the grid shown in the actual image was different than this.

## IIM AUDITORIUM

- Entire structure is to be hanged on picture clips.
- The structure is made up of water proof wooden board with golden metal strips that with that will be fixed on grooves made over the wood.
- The golden metal strips with shine with focus lights while the Kolkata skyline and grey sky will be painted on wood

Length: 9.1 m (30 ft)



Width 2.06 m (6.75 ft)

Area: 18.8 sqm (202 sqft)

Actual grid image (Referring to the golden metal strips in the back)  
 The skyline is different so please do not refer to this image for that.

❖ **Two quotes are required for Point 9.**

- 1) If the grills are not changed and the finish is made better.
- 2) If we replace the grills with golden metal strips as mention in the Image above.

The Artist/Vendor should visit the site (Metal House, Plot 13/4, Block AQ, Salt Lake, and Sec V Kolkata 700091) for proper understanding of the mural status.